



Bombardier Global 5000
SN 9798 N798BD

Specifications and Summary



GUARDIANJET

2017 BOMBARDIER GLOBAL 5000



OFFERED AT: \$27,495,000

HIGHLIGHTS:

- 15-Place Interior with Forward Galley
- Honeywell Jetwave KA Band WiFi
- Crew Force Measuring System
- Global Vision Flight Deck
- RRCC Engine Program
- Honeywell MSP APU Program
- Collins VENUE Cabin Management System
- Flap Corrosion Prevention and Drainage Improvement (SB 700-57-5005, -5008, -5009, -5010 and SB 700-55-5002)

STATUS: As of August 30th, 2024

TOTAL TIME: 2,095 Hours

LANDINGS: 786 Cycles

ENGINES: BR700-710A2-20 (CIMMS)

	Engine No. 1	Engine No. 2
TIME SINCE NEW:	2,095	2,095
CYCLES:	793	793
SERIAL NUMBER:	22727	22726
<i>Engines enrolled on Rolls Royce Corporate Care</i>		

APU: Honeywell RE220 (GX)

HOURS: 1,391

SERIAL NO: P-925

APU enrolled on Honeywell MSP

CAPABILITIES:

RVSM	CPDLC	HUD
WAAS/LPV	LINK 2000+	EVS
TAWS	TCAS II	SVS
Triple FMS	Autothrottle	MultiScan Weather Radar
Crew Force Measuring System	FDR	Windshear Escape
	Lightning Detection	QAR

AVIONICS & COCKPIT



AVIONICS: Bombardier Global Vision Flight Deck

ADC: Triple Collins ADC-3020 Air Data Computers

CVR: L3 FA2100 Cockpit Voice Recorder

DME: Dual Collins DME-4000 Radio Altimeter

ELT: ACR/Artex B406-4 ELT (406 MHz) w/ 110-328-01 Blade Antenna

FDR: L3 FA2100 Flight Data Recorder

FLIGHT DISPLAY: Four Collins AFD-6520 Adaptive Flight Displays

GPS: Dual Collins GPS-4000S GPS Receivers

HI FREQUENCY RECEIVER: Dual Collins HF-9031A w/ SELCAL

NAVIGATION RECEIVER UNIT: Dual Collins NAV-4000 Navigation Receiver (VOR/ILS/ADF)

RADIO ALTIMETER RECEIVER: Dual Collins ALT-4000 Radio Altimeter Transceiver

TCAS: Collins TSS-4100 TCAS II Processor

TRANSPONDER: Dual Collins TDR-94D Mode S Transponders

VHF COMMUNICATION UNIT: Triple Collins VHF-4000 Comm. Transceivers

WEATHER RADAR: Collins RTA-4118 Receiver/Transmitter (18 Inch Antenna)

MAINTENANCE & INSPECTION STATUS BREAKDOWN

- Maintenance Tracking by CAMP
- Engines enrolled on RRCC
- APU enrolled on Honeywell MSP

INSPECTION

15 Month Inspection
 30 Month Inspection
 60 Month Inspection
 120 Month Inspection
 180 Month Inspection

COMPLIED WITH

10-May-24
 02-Mar-23
 02-Mar-23
 N/A
 N/A

NEXT DUE

30-Jun-25
 30-Jun-25
 31-Dec-27
 31-Dec-27
 31-Dec-32



CABIN ENTERTAINMENT & COMMUNICATIONS

ENTERTAINMENT

- Two (2) Blu Ray Disc Players (Blu-ray/CD/DVD/MP3 Operations)
- Two (2) 10.6" Plug-In Touchscreen HD Monitors
- Thirteen (13) Mini i-Touch Devices w/Charging Cradles
- Two (2) Cockpit Multi-Function Touchscreen Displays
- One (1) 10.6" Touchscreen HD Monitor (Galley Annex)
- Two (2) Receptacles for 10.6" Plug-In Touchscreen HD Monitors
- Forward & Aft 24" HD Bulkhead Mounted Monitors



COMMUNICATIONS

- Honeywell JetWave High Speed KA Band
- Swift Broadband
- Inmarsat Satellite Communication System
- Iridium Telephone System w/Wireless Touchscreen Handsets
- SatCom Direct Router SDR

INTERIOR

INTERIOR DESCRIPTION

Original Interior

Fifteen (15) passenger cabin features four-place club (4), followed by a four-place (4) conference group across from a two-place divan (2). In the aft cabin there is a three-place (3) divan opposite a two-place club (2). The forward galley is equipped with a High Temp Oven, Food Chiller, Microwave, and Nespresso Coffee Maker. There are both forward and aft lavatories.



INTERIOR



INTERIOR



INTERIOR



EXTERIOR

EXTERIOR DESCRIPTION

(Original Paint)

Overall White with Dark and Light Blue Accent Striping



Prospective purchasers are encouraged to conduct their own independent pre-purchase inspection as this sheet makes no representations as to the airworthiness of the aircraft or the accuracy of the above information. Specifications subject to verification upon inspection. Aircraft subject to prior sale.

2024 09 10 / ZC